



Center City PCS [Shaw] - Lead in Water Test Results



FY21 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Draw A Sample ID	FT Final Results - Draw A (ppb)	Draw B Sample ID	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right						
Center City PCS [Shaw]	WS-072-001	Cooler	Basement	in hallway adjacent to girls' restroom 002	Low	Left	WF-022021-072001-03	N/A	FT-FY21-022021-072001-A	Non-Op	FT-FY21-022021-072001-B	Non-Op
Center City PCS [Shaw]	WS-072-002	Cooler	Basement	in hallway adjacent to girls' restroom 002	High	Right	WF-022021-072002-03	N/A	FT-FY21-022021-072002-A	Non-Op	FT-FY21-022021-072002-B	Non-Op
Center City PCS [Shaw]	WS-072-003	Food Prep Sink	Basement	In kitchen 007			WF-022021-072003-03	5/13/2021	FT-FY21-022021-072003-A	<1	FT-FY21-022021-072003-B	<1
Center City PCS [Shaw]	WS-072-004	Cooler	4	in hallway adjacent to stairwell	Low	Left	WF-022021-072004-04	N/A	FT-FY21-022021-072004-A	Non-Op	FT-FY21-022021-072004-B	Non-Op
Center City PCS [Shaw]	WS-072-005	Cooler	4	in hallway adjacent to stairwell	High	Right	WF-022021-072005-04	N/A	FT-FY21-022021-072005-A	Non-Op	FT-FY21-022021-072005-B	Non-Op
Center City PCS [Shaw]	WS-072-006	Bottle Filler	Basement	in hallway adjacent to girls' restroom 002	High	Left	WF-022021-072006-03	5/13/2021	FT-FY21-022021-072006-A	<1	FT-FY21-022021-072006-B	<1
Center City PCS [Shaw]	WS-072-007	Bottle Filler	4	in hallway adjacent to stairwell	High	Left	WF-022021-072007-03	5/13/2021	FT-FY21-022021-072007-A	<1	FT-FY21-022021-072007-B	<1