



Center City PCS [Trinidad] - Lead in Water Test Results



FY21 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Draw A Sample ID	FT Final Results - Draw A (ppb)	Draw B Sample ID	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right						
Center City PCS [Trinidad]	WS-044-001	Cooler	1	In hallway adjacent to room 102			WF-022021-044001-03	N/A	FT-FY21-022021-044001-A	Non-Op	FT-FY21-022021-044001-B	Non-Op
Center City PCS [Trinidad]	WS-044-003	Cooler	Basement	In hallway adjacent to B07			WF-022021-044003-03	5/2/2021	FT-FY21-022021-044003-A	<1	FT-FY21-022021-044003-B	<1
Center City PCS [Trinidad]	WS-044-004	Break Room	2	In room 202			WF-022021-044004-03	5/2/2021	FT-FY21-022021-044004-A	2.5	FT-FY21-022021-044004-B	<1
Center City PCS [Trinidad]	WS-044-005	Cooler	2	In hallway adjacent to room 203			WF-022021-044005-03	5/2/2021	FT-FY21-022021-044005-A	<1	FT-FY21-022021-044005-B	<1
Center City PCS [Trinidad]	WS-044-006	Cooler	Basement	In dance room B02A			WF-022021-044006-03	N/A	FT-FY21-022021-044006-A	Non-Op	FT-FY21-022021-044006-B	Non-Op
Center City PCS [Trinidad]	WS-044-007	Bottle Filler	1	In hallway adjacent to room 102			WF-022021-044007-02	5/2/2021	FT-FY21-022021-044007-A	<1	FT-FY21-022021-044007-B	<1
Center City PCS [Trinidad]	WS-044-008	Bottle Filler	2	In hallway adjacent to room 203			WF-022021-044008-02	5/2/2021	FT-FY21-022021-044008-A	<1	FT-FY21-022021-044008-B	<1
Center City PCS [Trinidad]	WS-044-009	Bottle Filler	Basement	In hallway adjacent to B07			WF-022021-044009-02	N/A	FT-FY21-022021-044009-A	Non-Op	FT-FY21-022021-044009-B	Non-Op